



64-805 Relief Valve

<u>Item No.</u>	<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>
1	64-820	Adjusting Stem Sub-Assembly	1
2	64-821	Lock Nut, Aluminum	1
3	64-822	Steel Screw	4
4	64-823	Bonnet, Aluminum	1
5	64-824	Adjusting Nut, SS	1
6	*64-825	Nylon Washer, Black	1
7	64-826	Spring Retainer, Aluminum	1
8	*64-827	Inside Spring	1
9	*64-828	Outside Spring	1
10	64-829	Guide Sleeve, Aluminum	1
11	*64-830	Diaphragm	1
12	64-831	Stop Spring, SS	1
13	*64-832	Back Up Seat, Black, Nylon	1
14	64-833	ScREW, SS	1
15	64-834	Chamber Insert, SS	1
16	64-835	Nylon Body, Black	1
17	64-836	Clamp Plate	1
	64-840	*Repair Kit includes Items 6, 8, 9, 11 and 13.	

**SDI Relief Valve
Part Number 64-805**

PI02/724jh